

RESOLUTION #4-2018/2019

WHEREAS: The Grundy County Board of Supervisors is empowered under authority of the Code of Iowa to impose weight limitations on highway structures under their jurisdiction.

NOW THEREFORE BE IT RESOLVED by the Grundy County Board of Supervisors that the following structures be posted at their listed load limits.

- Bridge located near W1/4 Corner, Sec. 3-89-15, Fairfield Township, (#A-04) – New Posting Load - “One Truck On Bridge”
- Bridge located near the N1/4 Corner, Sec.4-89-16, Beaver Township, (#B-03) – New Posting Load - 15 Tons
- Bridge located near the NW Corner, Sec.18-89-16, Beaver Township, (#B-10) – New Posting Load – 12-22-22 Tons
- Bridge located near the NW Corner, Sec.6-89-17, Pleasant Valley Township, (#C-04) – New Posting Load– 16-24-27 Tons
- Bridge located near the N1/4 Corner, Sec.11-89-17, Pleasant Valley Township, (#C-06) – New Posting Load – 14-24-26 Tons
- Bridge located near the NW Corner, Sec.28-89-17, Pleasant Valley Township, (#C-25) – New Posting Load– 20-33-34 Tons
- Bridge located near the W1/4 Corner, Sec.28-89-17, Pleasant Valley Township, (#C-26) – New Posting Load – 3 Tons
- Bridge located near the NW Corner, Sec.17-89-18, German Township, (#D-07) – New Posting Load – 10 Tons
- Bridge located near the N1/4 Corner, Sec.18-89-18, German Township, (#D-10) – New Posting Load – 8 Tons
- Bridge located near the N1/4 Corner, Sec.1-88-18, Shiloh Township, (#E-01) – New Posting Load– “One Truck on Bridge” & 22-36-34 Tons
- Bridge located near the W1/4 Corner, Sec.12-88-17, Colfax Township, (#F-12) – New Posting Load– 6 Tons
- Bridge located near the NW Corner, Sec.31-88-17, Colfax Township, (#F-23) – New Posting Load– 22-36-39 Tons
- Bridge located near the W1/4 Corner, Sec.23-88-15, Grant Township, (#H-15) – New Posting Load– 25-40-40 Tons
- Bridge located near the N1/4 Corner, Sec.14-87-15, Black Hawk Township, (#I-06) – New Posting Load– 19-30-35 Tons
- Bridge located near the Center, Sec.4-87-16, Washington Township, (#J-05) – New Posting Load– 20 Tons


- Bridge located near the Center, Sec.3-87-17, Palermo Township, (#K-2) – New Posting Load– 15-18-18 Tons
- Bridge located near the W1/4 Corner, Sec.13-87-17, Palermo Township, (#K-08) – New Posting Load– “One Truck on Bridge” & 23-34-34 Tons
- Bridge located near the W1/4 Corner, Sec.35-87-17, Palermo Township, (#K-12) – New Posting Load– 3 Tons
- Bridge located near the SW Corner, Sec.34-87-18, Melrose Township, (#L-19) – New Posting Load– 15-23-23 Tons

AND the following structures previously restricted load limits have been removed or will be removed due to repair or replacement:

- Bridge located near N 1/4 Corner, Sec. 36-89-16, Beaver Township, (#B-20) – New Posting - LEGAL BRIDGE
- Bridge located near NW Corner, Sec. 15-89-17, Pleasant Valley Township, (#C-11) – New Posting Load – LEGAL BRIDGE
- Bridge located near SW Corner, Sec. 8-88-18, Shiloh Township (#E-08) – New Posting Load – LEGAL BRIDGE
- Bridge Located near W 1/4 Corner Sec. 19-87 -17 Palermo Township (#K-09) – New Posting Load – LEGAL BRIDGE
- Bridge located near W 1/4 Corner Sec. 30, Clay Township (#N-17) – New Posting Load – LEGAL BRIDGE
- Bridge located near NE1/4 Corner, Sec. 3-87-15, Black Hawk Township, (#I-01) – New Posting - LEGAL BRIDGE
- Bridge located near the N1/4 Corner, Sec.14-87-15, Black Hawk Township, (#I-06) – New Posting Load– LEGAL BRIDGE

BE IT FURTHER RESOLVED that all resolutions or parts of resolutions in conflict with the provisions of this resolution are hereby repealed.

Passed and Approved this 23rd day of July, 2018.



 James Ross, Chairman
 Grundy County Board of Supervisors

ATTEST: 

 Rhonda R. Deters, Grundy County Auditor